Approved For Release 2003/01/24 : CIA-RDP63-09313A000600100113-0

able

25X1A

25X1A

25X1A

25X1A

25X1C

| MEMORANDUM FOR | : | Acting Chief, Development Projects Division | |
|---|---------------------------------------|--|--|
| SUBJECT | : | Pilot Availability for Detachment G 25X1A | |
| REFERENCE | : | Commander's Report, Detachment G, March 1962 dated 9 April 1962), Attached | |
| | | | Name of the Park o |
| of one element or regarding possi However, the re have noted a re and possibly lo of the North Vi | of ble fer cen nge etr | one of the referenced document served as a reminder to me my recent conversations utilization ence was not the only thing that brought this to mind. I at COMOR paper which establishes for at least three months, er, a continuing requirement for two overflights per month am area; I am aware, of course, of the continuing CINCLANT to NIMBUS flights per month; and on top of this is the conquirement for Detachment G. | _]5X1A _⊉5X1A |
| 2. Includ | | The stand up with the unit in the Far East. It is even | 25X1A |
| of L | | increase of activity in that area might result in a total being detailed to In addition ther two pilots at a minimum to satisfy the NIMBUS required goes on leave or gets sick, the reserve balance avail- | 25X1A |

18 May 1962

is fairly small.

Approved For Release 2003/01/24 : CIA-RDP63-00313A000600100113-0

IDEA-0772 Page 2

| 25X1C | | | |
|-------|--|-------|--|
| | | | |
| | | | |
| 25X1C | | | |
| | | | |
| | | 25X1A | TAMES A. CUNNINGHAM / DR. Assistant Chief, DPD |
| | 25X1A Attachment | | |
| | Distribution: 1 - AC/DPD, w/att 2 - ASST CH/DPD, w/o att 3 - DPD/SPB, w/o att 4 - DPD/SO, w/o att 5 - DPD/RI, w/o att | | |

DPD: JACunningham, Jr./mg

IDEA-0779 Copy 3 of 3

24 May 1962

| 25X1A | Dear | |
|-------|---|-------|
| 25X1A | This is in line with the procedure established by concerning abstracts of information from the Monthly Commander's Report which we feel are pertinent for your use. The senior communications offic at Det. "H" in his April 1962 monthly report has this to say: | |
| 25X1A | a. The originally received with Article 358 were badly dented. When | 25X1A |
| 25X1A | Article 352 was returned for IRAN the were removed and installed in Article | |
| 25X1A | 358. The damaged from 358 will be returned as soon as tests confirm the satisfactory operation of the presently installed units. | |
| | b. When making a thorough check of the cabling in recently-received Article 378, it was discovered that the RF cable to the ventral antenna had been out so short that maintenance efforts were rendered exceedingly difficult. The cable will be replaced during the next engine change. In order to prevent the frequently-encountered poor mechanical connection to the ventral antenna, the connectors on both Articles have been "potted". | |
| | Sincerely yours, | 25X1A |
| | ı | |

Approved For Release 2003/04/24 CIA-RDP63-00313A000600100113-0

(LAC)

25X1A

25X1A

Cy 1 -

2 - C/MS/DPD 3 - RI/DPD

MS/DPD Dist: